

OUT61946

P 102321Z MAY 67

FM NPIC WASHDC

TO RUCAAA/SAC OFFUTT AFB OMAHA NEB

RUCVAAA/4080 STRAT WG OL 19 BARKSDALE AFB LA

RUCVAAA/2D RTS BARKSDALE AFB LA

RUEPJS/DIA WASHDC

RUCIJRA/NAVRECONTECHSUPPCEN SUITLAND MD

RUEPIA/CIA WASHDC

RUWBKNA/15TH AF MARCH AFB RIVERSIDE CALIF

RUCVAAA/2 AF BARKSDALE AFB LA

BT

S E C R E T CITE NPIC 0611.

1967 MAY 10 23 40Z

11 MAY 1967

DISTRIBUTION		
By No.	Official	Action
2	File	
	OS	
	SEC BR	
	TDS	
	CSD	
	IFD	
	FD	
	PSD	
	PPM-CB	
	TID	
	IAP	
	PAS	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy
Captioned

15TH AF (FOR DI), SAC (FOR DIM/GLASS LAMP/DOCR, DM 4)

2D AF (FOR DI).

1. CAMERA B 7 WAS USED ON MISSION G-959 FLOWN ON 9 MAY 1967. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

2. ORIGINAL NEGATIVE:

A. RESOLUTION AND DENSITY ARE GOOD.

B. 9R SIDE: FRAMES 894, 895 AND 896 CONTAIN MINOR DEGRADATIONS INDUCED DURING PROCESSING; WATER OR CHEMICALS WERE SPLASHED ON PORTIONS OF THESE THREE FRAMES. THERE ARE MANUFACTURING SPLICES IN FRAMES 1003 AND 1293, A HEAT SPLICE IN FRAME 857 AND BETWEEN FRAMES 601/602, AND 1670/1671.

C. 9L SIDE: THERE ARE TWO PLUS DENSITY LINES, 1.7 AND 4.5 INCHES FROM AND PARALLEL TO THE INBOARD EDGE THROUGHOUT THE MISSION. EDGE CRIMPING IS NOTED ALONG THE OUTBOARD EDGE FROM FRAME 879 TO 900. THERE IS A HEAT SPLICE IN FRAME 878.

D. BOTH SIDES: THE EVENTS COUNTER BECAME ERRATIC AFTER FRAME 358 AND EVENTUALLY STUCK AT NUMBER 408 WHERE

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

IT REMAINED FOR THE BALANCE OF THE MISSION. FRAME 704,
708 AND 712 CONTAIN A CHANGE IN DENSITY WHICH HAS BEEN
ATTRIBUTED TO WINDOW REFLECTIONS IN PREVIOUS EVALUATIONS.
THE CYCLE RATE IS 4.5 SECONDS WITH APPROXIMATELY 60 PERCENT
OVERLAP IN THE VERTICAL FRAMES. THE LAST TITLED FRAME IS
1787.

3. POSITIVE:

- A. THE RESOLUTION AND DENSITY ARE GOOD.
- B. THE PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE APPROXIMATELY 25 PERCENT OF THE MISSION.

GP-1

S E C R E T

-END OF MESSAGE-